

**TRANSMISSION—SHIFT LEVER—SEPARATES FROM
ITS HOUSING**

**Article No.
91-1-11**

MERCURY: 1991 CAPRI

ISSUE

The shift lever may separate from its housing and drop out of position. This occurs because the shift housing insulator bonding fails.

ACTION

Install a new shift lever. Refer to the 1991 Capri Shop Manual, Section 16-37, for service details.

PART NUMBER	PART NAME
E9JY-7L257-A	Shift Lever

OTHER APPLICABLE ARTICLES: None

WARRANTY STATUS: Eligible Under Basic
Warranty Coverage

OPERATION	DESCRIPTION	TIME
910111A	Install Shift Lever	0.9 Hr.

DEALER CODING

BASIC PART NO.
7L257

OASIS CODES: 501000, 505200

CONDITION
CODE
01