

CONVERTIBLE TOP—BACKLITE SEPARATES FROM TOP**Article No.
91-12-3****MERCURY:** 1991 CAPRI**ISSUE**

The convertible backlite may separate from the convertible top. This occurs because of insufficient overlap of the backlite when the original top seam was completed. Since the backlite is not a separate serviced item, the entire convertible top must be replaced.

ACTION

Install a new convertible top. Refer to the 1991 Capri Shop Manual, Section 47-07, for service details.

OTHER APPLICABLE ARTICLES: None**WARRANTY STATUS:** Eligible Under Basic
Warranty Coverage

OPERATION	DESCRIPTION	TIME
911203A	Install Convertible Top	2.7 Hr.

DEALER CODING

BASIC PART NO.
7052700

CONDITION
CODE
01

OASIS CODES: 105000, 102000

PART NUMBER	PART NAME
FOJY-7652700-A8F	Convertible Top Cover