

<ul style="list-style-type: none"> • GLASS —FRONT DOOR—REVISED REGULATOR TO IMPROVE RISE TIME AND CLOSING PERFORMANCE • WINDOW—POWER—FRONT DOOR—REVISED REGULATOR TO IMPROVE RISE TIME AND CLOSING PERFORMANCE 	Article No. 91-12-4
--	--------------------------------

MERCURY: 1991 CAPRI

ISSUE

A more powerful and moisture resistant power window regulator is now available for service use.

ACTION

If service is required, refer to the following service procedure.

1. Ensure that the service action described in TSB 90-25-7 has been performed to preclude glass and weatherstrip alignment type concerns.
2. If the window continues to be slow to rise and does not close properly, install a new front door window regulator. Refer to the 1991 Capri Shop, Page 4-2-08, for service details.

OTHER APPLICABLE ARTICLES: 90-25-7

WARRANTY STATUS: Eligible Under Basic Warranty Coverage

OPERATION	DESCRIPTION	TIME
911204AT	Replace Window Regulator - Both Sides	1.4 Hr.
911204A	Replace Window Regulator - One Sides	0.8 Hr.

DEALER CODING

BASIC PART NO.
7023208

OASIS CODES: 102000, 205000

CONDITION
CODE
53

PART NUMBER	PART NAME
FOJY-7623200-A	Front Door Window Regulator - RH
FOJY-7623201-A	Front Door Window Regulator - LH