

<ul style="list-style-type: none"> • SUN VISOR—BLACK COLOR IS OBSOLETE—REPLACEMENT COLOR • TRIM —INTERIOR—SUN VISOR BLACK COLOR IS NO LONGER AVAILABLE 	Article No. 91-2-4
--	-------------------------------

MERCURY: 1991 CAPRI

ISSUE

The black sun visor is obsolete and no longer available for service. The replacement color is iron bark (gray).

ACTION

Use the iron bark color sun visors as replacements for the black sun visors. Both the LH and RH sun visors will require replacement with the iron bark color. Refer to the following Parts Block for correct parts usage.

OTHER APPLICABLE ARTICLES: None
WARRANTY STATUS: Eligible Under Basic Warranty Coverage

OPERATION	DESCRIPTION	TIME
910204A	Install One Or Both Sun Visors	0.4 Hr.

DEALER CODING

BASIC PART NO.
7004104
OASIS CODES: 107000

CONDITION CODE
38

PART NUMBER	PART NAME
FOJY-7604104-AVP	Sun Visor, RH (Turbo & Non-Turbo Units)
FOJY-7604105-AVP	Sun Visor, LH (Turbo Only)
FOJY-7604105-CVP	Sun Visor, LH (Non-Turbo)