

- **LEAKS—COOLANT—FROM RADIATOR HOSES**
- **RADIATOR—HOSES WITH REDUCED INSIDE DIAMETER—AVAILABLE FOR SERVICE**

**Article No.
91-20-7**

MERCURY: 1991 CAPRI

ISSUE

Coolant may leak from the upper or lower radiator hoses because the inside diameter of the hose is too large.

ACTION

Install new radiator hoses with reduced inside diameter for improved sealing performance. The hose clamps are unchanged. Refer to the 1991 Capri Service Manual, Section 27-03, for details.

PART NUMBER	PART NAME
FOJY-8260-A	Radiator Hose - Upper
FOJY-8286-A	Radiator Hose - Lower

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under Basic
Warranty Coverage

OPERATION	DESCRIPTION	TIME
912007A	Upper Radiator Hose - Replace	0.4 Hr.
912007B	Lower Radiator Hose - Replace	0.5 Hr.
912007C	Both Radiator Hoses - Replace	0.6 Hr.

DEALER CODING

BASIC PART NO.
8260

OASIS CODES: 402000

CONDITION
CODE
47