

FORD: 1981-1999 ESCORT
1983-1999 CROWN VICTORIA
1984-1988 EXP
1984-1994 TEMPO
1985-1999 TAURUS
1986-1997 PROBE
1988-1991 FESTIVA
1993-1999 MUSTANG
1994-1997 ASPIRE
1995-1999 CONTOUR
1996-1997 THUNDERBIRD
1981-1996 BRONCO
1981-1997 F SUPER DUTY, F-250 HD, F-350
1981-1999 ECONOLINE, F-150, F-250 LD
1983-1999 RANGER
1984-1990 BRONCO II
1984-1997 AEROSTAR
1991-1999 EXPLORER
1995-1999 WINDSTAR
1997-1999 EXPEDITION
1999 SUPER DUTY F SERIES
1984-1999 F & B SERIES
1988-1997 CARGO SERIES
1996-1998 AEROMAX, LOUISVILLE

LINCOLN: 1983-1999 CONTINENTAL
1988-1992 MARK VII
1993-1998 MARK VIII
1996-1997 TOWN CAR
1998-1999 NAVIGATOR

MERCURY: 1983-1999 GRAND MARQUIS
1984-1986 CAPRI
1984-1987 LN7
1984-1994 TOPAZ
1985-1999 SABLE
1991-1994 CAPRI
1993-1999 TRACER
1995-1999 MYSTIQUE
1996-1997 COUGAR
1999 COUGAR
1993-1999 VILLAGER
1997-1999 MOUNTAINEER

MERKUR: 1985-1988 XR4TI
1988 SCORPIO

ISSUE

Ford Motor Company has released a new Electrical Grease (F8AZ-19G208-AA) to reduce the possibility of moisture corrosion at the terminals.

ACTION

Add the new grease during electrical connection repair.

CAUTION

ELECTRICAL CONNECTOR GREASE SHOULD NOT BE USED IN HIGH VOLTAGE CONNECTIONS FOR SPARK PLUG AND COIL WIRE APPLICATIONS.

PROPER USES OF THE NEW ELECTRICAL GREASE INCLUDE:

- Electrical Connectors
- Battery Connections
- Light Sockets
- Starter Terminals

DO NOT USE ON:

- Spark Plug Wires
- Coil Wires
- Spark Plug-to-Coil Connections
- Low Current Flow Switches (12V Systems less than 0.1 amp)

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: INFORMATION ONLY

OASIS CODES: 201000, 201100, 201200, 202000,
203000, 203200, 204000, 205000,
601300