Article No. 96-15-6

AIR CONDITIONING—FILTERING REFRIGERANT— SYSTEM FLUSHING—TRACER DYE—LEAK TESTING—O-RING TOOL—TSB REPUBLICATION TO INCLUDE LATEST MODEL YEAR

FORD: 1980-97 CROWN VICTORIA

1981-97 ESCORT 1982-83 FAIRMONT

1982-88 EXP

1982-97 MUSTANG, THUNDERBIRD

1983-86 LTD 1984-94 TEMPO 1986-97 TAURUS 1988-93 FESTIVA 1989-97 PROBE 1994-97 ASPIRE 1995-97 CONTOUR

LINCOLN-MERCURY: 1980-97 GRAND MARQUIS, TOWN CAR

1982-83 ZEPHYR 1982-86 CAPRI 1982-87 LN7

1982-97 CONTINENTAL, COUGAR

1983-86 MARQUIS 1984-92 MARK VII 1984-94 TOPAZ 1986-97 SABLE 1991-94 CAPRI 1991-97 TRACER 1993-97 MARK VIII 1995-97 MYSTIQUE

LIGHT TRUCK: 1980-96 BRONCO

1980-97 ECONOLINE, F-150-350 SERIES

1983-97 RANGER 1984-90 BRONCO II 1986-97 AEROSTAR

1988-97 F-47

1991-97 EXPLORER 1993-97 VILLAGER 1995-97 WINDSTAR

1997 EXPEDITION, MOUNTAINEER

AIR CONDITIONING—FILTERING REFRIGERANT—SYSTEM FLUSHING—TRACER DYE—LEAK TESTING—O-RING TOOL—TSB REPUBLICATION TO INCLUDE LATEST MODEL YEAR

Article No. 96-15-6 Cont'd.

ISSUE: This TSB article is being published to inform technicians to refer to the following list of TSB's when performing service on an A/C system. These TSB's apply to all model year vehicles. These procedures also appear in the appropriate model/year Service Manuals and the procedures must be followed.

ACTION: Refer to the following list of TSB's when performing service to a vehicle's A/C system.

• 95-25-3 - Refrigerant Identification

• 96-15-5 - A/C System Filtering

• 95-18-4 - A/C System Flushing

• 95-21-4 - A/C System Tracer Dye

• 95-13-1 - A/C Evaporator Leak Test

• 95-2-2 - Plastic O-ring Tool

OTHER APPLICABLE ARTICLES: 95-13-1,

95-18-4, 95-2-2,

95-21-4,

95-25-3,

96-15-5

WARRANTY STATUS: INFORMATION ONLY

OASIS CODES: 208000, 208999